Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule

Product Notes



Copyright © 2009, 2010, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related software documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT RIGHTS Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle USA, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications which may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure the safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle is a registered trademark of Oracle Corporation and/or its affiliates. Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. UNIX is a registered trademark licensed through X/Open Company, Ltd.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.





Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule Product Notes

This document provides news and issues about installation and use of Oracle's Sun Dual Port 4x DDR IB Host Channel Adapter PCIe ExpressModule.

- "Hardware and Software Requirements" on page 2
- "Downloading Firmware" on page 2
- "Solaris 10 10/09 Issues" on page 3
- "Older Firmware Issue" on page 5
- "Third-Party Web Sites" on page 5
- "Documentation Feedback" on page 5

Hardware and Software Requirements

Before using the Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule, ensure that your system meets the following hardware and software requirements.

TABLE 1 Hardware and Software Requirements

Supported Hardware	Supported Operating Systems	Other Software
Sun Blade X6270 Sun Blade X6440 Sun Blade X6240 Sun Blade T6340 and other Sun Blade servers	Solaris 10 10/09 Operating System Red Hat Enterprise Linux 4-U6 (32-bit and 64-bit) Red Hat Enterprise Linux 4-U7 (32-bit and 64-bit; on PCIe Gen-2 platforms) Red Hat Enterprise Linux 5.1 (64-bit) Red Hat Enterprise Linux 5.2 (64-bit) Red Hat enterprise Linux 5.3 (64-bit; on PCIe Gen-2 platforms) SUSE Linux Enterprise Server 10 SP1 (64-bit) SUSE Linux Enterprise Server 10 SP2 (64-bit; on PCIe Gen-2 platforms)	SUNWhermon package provides the required driver (hermon) for the Solaris OS MLNX-OFED 1.3.1 or higher must be used with any Linux distribution.

The preceding information is up-to-date at the time this manual was written. Go to http://www.sun.com for the latest information. Subsequent versions of this document have a higher number following the final dash. That is, 820-6540-11 becomes 820-6540-12.

Downloading Firmware

The most recent firmware for this InfiniBand ExpressModule (Sun X41216A-Z) is available at:

http://www.mellanox.com/support/firmware table Sun.php

Select the software and documentation downloads in the row of the table with the following description: Dual 20Gigabit/Sec 4X InfiniBand Host Channel Adapter PCI Express ExpressModule, RoHS.

To install the firmware, refer to the release notes at this Mellanox site.

Solaris 10 10/09 Issues

Kernel Could Panic After 1-2 Hours of Running Heavy IPoIB Traffic Sun Blade T6340 Servers (CR 6878568)

In test environments on Sun Blade T6340 servers under extreme IPoIB load, the Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule could report a CQE Local Protection Error (HCA reported error) followed by a system panic due to an error reported in the PCIe root complex.

If this issue occurs, messages similar to the following are displayed:

```
Feb 27 03:55:03 c145-8 hermon: NOTICE: hermon0: Device Error: CQE local protection error panic[cpu91]/thread=2a1029a3ca0: Fatal error has occured in: PCIe root complex.(0x10)(0x0)

(There may be additional information intervening between these two messages.)
This has been identified as being a result of a patch that was recommended for IB users of Solaris 10/09:
Sparc system: patch 143352-01
x86 sytems: patch 143353-01
```

Note – This issue has not been reported in a customer environment.

Workaround: If the CQE Local Protection Error followed by a PCIe panic does occur, reboot the system and check to see if the affected patch (143352 SPARC or 143353 x86) is installed on your system. Use the showrev command:

```
# showrev - p | grep "Patch: 143352"
```

Or:

```
# showrev - p | grep "Patch: 143353"
```

If the patch has been installed, remove the patch with the patchrm command and reboot the system. You might see slightly decreased performance in some networking operations over InfiniBand as a result of removing this patch.

If the panic occurs and this patch is not installed, inform your authorized Oracle service representative of the failure and provide the available details.

Third-Party HCA Firmware Issue (CR 6915273)

This issue applies to third-party HCAs (QDR HCAs) that are equivalent to the Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule.

In some cases, running with less than the most current firmware on a QDR HCA could result in a panic because the firmware incorrectly reports an error. If the error occurs, you see a message similar to the following:

```
panic[cpu3]/thread=ffffffe80000d1c60: Hermon Fatal Internal Error.
Hermon state=0xfffffffff800e2000
```

In the message log a message similar to the following is displayed:

```
NOTICE: hermon0: Device Error: EQE hca internal error
```

Workaround: This issue is unlikely to occur with legacy Sun HCAs or new HCAs from Oracle, because these HCAs ship with the current firmware. If this error does occur, reboot the system and use the firmwareflash command to display the current firmware version. The minimum firmware version must be 2.7.000.

```
# firmwareflash -1 -c IB

Device[101] /devices/pci@0,0/pci10de,377@f/pci15b3,634a@0:devctl
Class [IB]

GUID: System Image - 0003ba000100cda7

Node Image - 0003ba000100cda4

Port 1 - 0003ba000100cda5

Port 2 - 0003ba000100cda6

Firmware revision : 2.7.000

Product : 375-3549-01 (Sun PCIe DDR X4217A)

PSID : SUN0070000001
```

If the firmware is not at Version 2.7.000 or higher, refer to the user's guide for obtaining and updating the firmware on all HCAs in the system. Once updated, reboot the system to enable the new firmware.

If this problem occurs on a system in which all HCAs are already at this minimum firmware revision, inform your authorized Oracle service representative of the failure and provide the available details.

Older Firmware Issue

Boot Over InfiniBand Component of the Firmware Could Exceed the Option ROM Capacity (CR 6800225)

On some platforms, certain option cards might not get initialized due to the host channel adapter (HCA) taking most of the available Option ROM space in the BIOS.

Workaround: Check for and install a later version of the HCA firmware at http://www.sun.com.

Third-Party Web Sites

Sun is not responsible for the availability of third-party web sites mentioned in this document. Sun does not endorse and is not responsible or liable for any content, advertising, products, or other materials that are available on or through such sites or resources. Sun will not be responsible or liable for any actual or alleged damage or loss caused by or in connection with the use of or reliance on any such content, goods, or services that are available on or through such sites or resources.

Documentation Feedback

Sun is interested in improving its documentation and welcomes your comments and suggestions. You can submit your comments by going to:

http://www.sun.com/hwdocs/feedback

Please include the title and part number of your document with your feedback:

Oracle's Sun Dual Port 4x QDR IB Host Channel Adapter PCIe ExpressModule Product Notes, part number 820-6540-12