

Oracle VTS 7.0 Patch Set 15 Software

Release Notes



Part No. E37511-02
February 2013

Copyright © 2011, 2013 Oracle and / or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related software documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT RIGHTS. Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle USA, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications which may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure the safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and / or its affiliates. Other names may be trademarks of their respective owners.

AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. UNIX is a registered trademark licensed through X/Open Company, Ltd.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.

Copyright © 2011, 2013 Oracle et / ou ses affiliés. Tous droits réservés.

Ce logiciel et la documentation qui l'accompagne sont protégés par les lois sur la propriété intellectuelle. Ils sont concédés sous licence et soumis à des restrictions d'utilisation et de divulgation. Sauf disposition de votre contrat de licence ou de la loi, vous ne pouvez pas copier, reproduire, traduire, diffuser, modifier, breveter, transmettre, distribuer, exposer, exécuter, publier ou afficher le logiciel, même partiellement, sous quelque forme et par quelque procédé que ce soit. Par ailleurs, il est interdit de procéder à toute ingénierie inverse du logiciel, de le désassembler ou de le décompiler, excepté à des fins d'interopérabilité avec des logiciels tiers ou tel que prescrit par la loi.

Les informations fournies dans ce document sont susceptibles de modification sans préavis. Par ailleurs, Oracle Corporation ne garantit pas qu'elles soient exemptes d'erreurs et vous invite, le cas échéant, à lui en faire part par écrit.

Si ce logiciel, ou la documentation qui l'accompagne, est concédé sous licence au Gouvernement des Etats-Unis, ou à toute entité qui délivre la licence de ce logiciel ou l'utilise pour le compte du Gouvernement des Etats-Unis, la notice suivante s'applique :

U.S. GOVERNMENT RIGHTS. Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle America, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

Ce logiciel ou matériel a été développé pour un usage général dans le cadre d'applications de gestion des informations. Ce logiciel ou matériel n'est pas conçu ni n'est destiné à être utilisé dans des applications à risque, notamment dans des applications pouvant causer des dommages corporels. Si vous utilisez ce logiciel ou matériel dans le cadre d'applications dangereuses, il est de votre responsabilité de prendre toutes les mesures de secours, de sauvegarde, de redondance et autres mesures nécessaires à son utilisation dans des conditions optimales de sécurité. Oracle Corporation et ses affiliés déclinent toute responsabilité quant aux dommages causés par l'utilisation de ce logiciel ou matériel pour ce type d'applications.

Oracle et Java sont des marques déposées d'Oracle Corporation et / ou de ses affiliés. Tout autre nom mentionné peut correspondre à des marques appartenant à d'autres propriétaires qu'Oracle.

AMD, Opteron, le logo AMD et le logo AMD Opteron sont des marques ou des marques déposées d'Advanced Micro Devices. Intel et Intel Xeon sont des marques ou des marques déposées d'Intel Corporation. Toutes les marques SPARC sont utilisées sous licence et sont des marques ou des marques déposées de SPARC International, Inc. UNIX est une marque déposée concédée sous licence par X/Open Company, Ltd.



Oracle VTS 7.0 Patch Set 15 Software Release Notes

These sections describe new features and issues related to Oracle VTS 7.0, Patch Set 15 software:

- “Late-Breaking Information” on page 2
- “Known Issues in PS15 Release (February 2013)” on page 3
- “Known Issues in PS15 Release (October 2012)” on page 5
- “Documentation, Feedback and Support” on page 10

Currently, a newer version Oracle VTS 7.0 PS15 is available, and it is highly recommended for users running the previous version of PS15 release. Oracle Solaris 10 users can use the patch ID 149395-02 to update to this newer version. Whereas, for Oracle Solaris 11 users, the package to update to this new release is available from S11.1 SRU4.

You can use the following command line entries to identify which version of Oracle VTS 7.0 PS15 you are using:

- `.version file`
- `./testname -v`
- `pkgparam -v SUNWvts | grep PROVERS`

For example, the output of `.version file` command can be, `7.0 PS15.1` or `7.0PS15` depending on the PS 15 release being used.

Late-Breaking Information

Patch Set 15 Changes

The following changes were made to the harness and CPU diagnostics:

- Improved quality and performance of VTS libraries.
- Support added for retrieving package versioning information on an installed system.
- Harness enhance to support mapping of multiple tests to SYSTEM BUS for interconnect LT option
- New subtests (march, hammer, and stress) made available for X86.

The following changes were made to the input/output diagnostics:

- networktest enhanced to log kstat data.
- Support to allow sunvts the capability to run an extended inquiry, greater than 36bytes against SAS SSD.
- VTS tests for Qlogic and Emulex enhanced to support Ganymede HBAs.
- Specialized SunVTS SSD profiles added which could maximize Reads or Write.
- diskmediatest enhanced to read inquiry details of the disks connected behind raid controller card and Multi-path automate write-read paths for all the channels.

Documentation Changes

- Two new procedures added explaining how to run hlgraphics test and check presence of ast driver on T4 systems.
- Added a new section explaining the user patterns support for diskmedia test.
- Added new configuration parameters to VTS harness, disk test, and network test configuration files.

Note – This is a summary of some changes to the *Oracle VTS 7.0 User Guide for Patch Set 8 and Subsequent Compatible Releases*. This is not a complete list of all changes.

Known Issues in PS15 Release (February 2013)

This section describes the known issues in Oracle VTS 7.0 PS15 released in February:

IB-CX2 Failing for sunvts networktest (Bug 16068487)

IB-CX2 fails for sunvts networktest on SPARC T4-1B and next generation SPARC blade platforms.

Workaround:

Plumb the IB ports before running Network test. You may verify if all IB ports are plumbed up by running `ifconfig -a`. When all IB ports are listed with IP addresses, then nettest will start on them rather than networktest.

Running Internal Loopback (stress) for 18 Hours on 8 Niantic Cards saw 8 Errors (Bug 16041792)

When Oracle VTS networktest internal loopback testing is run on "Sun Dual Port 10GbE PCIe 2.0 Networking Cards with Intel 82599 10GbE Controller" for longer duration, it might fail intermittently with following error. This failure does not affect normal usage of the networking card.

```
01/28/13 14:44:22 sca-t5-8-0.us.oracle.com SunVTS7.0ps15: VTSID  
6001 Network.networktest.ERROR ixgbe6  
(/devices/pci@3c0/pci@1/pci@0/pci@e/network@0:ixgbe6): "Failed to  
read the data in loopback mode Internal on ixgbe (Intel 10Gb  
Ethernet 1.1..Packets dropped : 101, Total Packet Transmitted :  
101"  
01/28/13 14:44:24 sca-t5-8-0.us.oracle.com SunVTS7.0ps15: VTSID  
6427 vtsk.ERROR : Network.networktest.0[ixgbe6] (pid=6063) exited  
with exit code: -1
```

Workaround:

None.

VTS Network Test Fatal due to DLPI Calls for Physical Address Fails on igb port (Bug 16215995)

When VTS.networktest runs loopback test multiple times on multiple igb ports in Component Stress mode, the igb device goes into an unknown state and stops responding to basic DLPI calls for physical address.

Workaround:

None.

vtsk Probes and Runs networktest on Interfaces Part of Plumbed Aggregated Link (Bug 16092803)

The networktest is designed to run only on unplumbed interfaces on the system, but vtsk probes and starts networktest on the interfaces which are part of the Aggregated-Interface(plumbed). The networktest fails with the following error message.

```
01/09/13 02:02:11 sca-t5-2-2.us.oracle.com SunVTS7.0ps15build14:  
VTSID 6000 Network.networktest.ERROR ixgbe2  
(/devices/pci@3c0/pci@1/pci@0/pci@1/network@0:ixgbe2): "Cannot  
set loopback mode : Auto on device ixgbe2.Probable_Cause(s) :<No  
loopback plug or cable> <Bad loopback plug or  
cable>Recommended_Action(s) :<If test fails, check loopback plug or  
cable.>"  
01/09/13 02:02:12 sca-t5-2-2.us.oracle.com SunVTS7.0ps15build14:  
VTSID 6427 vtsk.ERROR : Network.networktest.0[ixgbe2] (pid=3469)  
exited with exit code: -1
```

Workaround:

None.

Known Issues in PS15 Release (October 2012)

This section describes the known issues.

Sunvts 7.0PS15 Binary run Problem in X4440 With RM_Disk_Ignore_Target (Bug 15821322)

If there is an entry, RM_Disk_Ignore_Target All=Ignore, set in the /etc/sunvts/conf/sunvts.conf file then Diskmediatest fails with the following message:

```
VTSID 8009 diskmediatestmfq.FATAL : "Failed to open the device node, Error Message : (Device busy)
```

Workaround:

Disable the vold or volfs process, if running.

Interconnect.ramtest Fails on OPL System (Bug 15818252)

The ramtest fails on an OPL system, because the memloops option for ramtest is removed from the binary but not from the profiles.

Workaround:

Run Interconnect LT with IO Bus option only.

fputest Fails With SIGILL on Fujitsu M10 Processors (Bug 15989998)

The test tries to execute an instruction that is not supported by the Fujitsu M10 processors. It uses getisax(2) and checks for a specific bit-mask in the result to check if the instruction is supported. The instruction was supported in an earlier UltraSPARC processor but is not present in the recent ones. The bit-mask

representing this instruction has been re-used to represent a different set of instructions on Fujitsu M10 systems. Seeing it in the result of getisax(2), fputest assumes that the original UltraSPARC instruction is available in the system and tries to execute it, which leads to the SIGILL.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

dtlbtest Fails With a FATAL Message on Fujitsu M10 Processors (Bug 16008435)

The dtlbtest fails with a fatal message on the new Fujitsu M10 processors.

```
Page size 64KB not supported on this OS version or unavailable for given TLB (TLB-ALL) for CPU model (SPARC64-X)
```

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Test Probe testprobe_ramtest() FailedWith Segmentation Violation on Fujitsu M10 Systems (Bug 15955560)

The libvtssysinfo does not recognize Fujitsu M10 processors and hence returns -1 for all APIs. l3sramtest_probe does not handle the libvtssysinfo failures and continues to run even after the libvtssysinfo API fails.

```
VTS sysinfo Library function vts_tlib_get_onln_cpus failed; Return value is -1; vtssysinfo: some problem encountered while caching the info errno=6,errstr=No such device or address  
ERROR: Test probe testprobe_l3sramtest() Failed with segmentation violation (signal: 10)
```

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Oracle VTS 7.0 ps15 Core due to SIGSEGV Signal at Execution on Fujitsu M10 Systems (Bug 15887244)

Oracle VTS 7.0 PS15 does not recognize ORCL.SPARC64-X token name and fails to compare platform name. When the vts command tries to compare ORCL, SPARC64-X by `strncpy(3C)` in `__1cEUtlTcreateDumpOfProfile6M_i_()`, it accesses NULL pointer.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Processor LT may Hang (Bug 15826050)

Processor LT might get stopped during cleanup waiting for mutex lock.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Network.networktest.ERROR net2 Failed to Create the Directory /var/sunvts/logs/networktest.kstat/ (Bug 15823896)

The networktest fails net2, and hence the `/var/sunvts/logs/networktest.kstat/` directory is not created.

Workaround:

Remove the `networktest.kstat` directory under `/var/sunvts/logs` and create a new directory with the same name and restart vtsk.

Interconnect.networktest.ERROR. Failed to Read the Data in Loopback Mode Auto on ixgbe (Bug 15823894)

networktest fails to read data in Auto(External) loopback mode on ixgbe port, and displays the following error message.

```
Interconnect.networktest.ERROR. Failed to Read the Data in  
Loopback Mode Auto on ixgbe
```

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Networktest Probe Takes Long Time on Systems Having Higher Number of Ports (Bug 15889513)

This issue is seen on systems containing more than 100 network ports, and the networktest probe takes more time and appears to have stopped.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

T5-8 Sunvts cddvdtest fails on USB3.0 DVD drive testing DVD-R media (Bug 15939411)

By default, the cddvdtest fails on USB3.0 drive testing on DVR-R media.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Networktest probe core dumps on system (Bug 16021896)

The networktest probe core dumps on systems having a higher number of ports.

Workaround:

Update to the latest version of Oracle VTS 7.0 PS15 release.

Documentation, Feedback and Support

For the latest versions of all of Oracle VTS documents, go to:

<http://www.oracle.com/pls/topic/lookup?ctx=OracleVTS7.0>

These web sites provide additional resources:

- Documentation <http://www.oracle.com/technetwork/indexes/documentation/index.html>
- Support <https://support.oracle.com>
- Training <https://education.oracle.com>