

Sun Netra Data Plane Software Suite 2.1 Update 1

Release Notes



Part No. 820-5157-11
April 2010, Revision A

Copyright © 2009, 2010, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related software documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT RIGHTS. Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle USA, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications which may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure the safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. UNIX is a registered trademark licensed through X/Open Company, Ltd.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.

Copyright © 2009, 2010, Oracle et/ou ses affiliés. Tous droits réservés.

Ce logiciel et la documentation qui l'accompagne sont protégés par les lois sur la propriété intellectuelle. Ils sont concédés sous licence et soumis à des restrictions d'utilisation et de divulgation. Sauf disposition de votre contrat de licence ou de la loi, vous ne pouvez pas copier, reproduire, traduire, diffuser, modifier, breveter, transmettre, distribuer, exposer, exécuter, publier ou afficher le logiciel, même partiellement, sous quelque forme et par quelque procédé que ce soit. Par ailleurs, il est interdit de procéder à toute ingénierie inverse du logiciel, de le désassembler ou de le décompiler, excepté à des fins d'interopérabilité avec des logiciels tiers ou tel que prescrit par la loi.

Les informations fournies dans ce document sont susceptibles de modification sans préavis. Par ailleurs, Oracle Corporation ne garantit pas qu'elles soient exemptes d'erreurs et vous invite, le cas échéant, à lui en faire part par écrit.

Si ce logiciel, ou la documentation qui l'accompagne, est concédé sous licence au Gouvernement des Etats-Unis, ou à toute entité qui délivre la licence de ce logiciel ou l'utilise pour le compte du Gouvernement des Etats-Unis, la notice suivante s'applique :

U.S. GOVERNMENT RIGHTS. Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle America, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

Ce logiciel ou matériel a été développé pour un usage général dans le cadre d'applications de gestion des informations. Ce logiciel ou matériel n'est pas conçu ni n'est destiné à être utilisé dans des applications à risque, notamment dans des applications pouvant causer des dommages corporels. Si vous utilisez ce logiciel ou matériel dans le cadre d'applications dangereuses, il est de votre responsabilité de prendre toutes les mesures de secours, de sauvegarde, de redondance et autres mesures nécessaires à son utilisation dans des conditions optimales de sécurité. Oracle Corporation et ses affiliés déclinent toute responsabilité quant aux dommages causés par l'utilisation de ce logiciel ou matériel pour ce type d'applications.

Oracle et Java sont des marques déposées d'Oracle Corporation et/ou de ses affiliés. Tout autre nom mentionné peut correspondre à des marques appartenant à d'autres propriétaires qu'Oracle.

AMD, Opteron, le logo AMD et le logo AMD Opteron sont des marques ou des marques déposées d'Advanced Micro Devices. Intel et Intel Xeon sont des marques ou des marques déposées d'Intel Corporation. Toutes les marques SPARC sont utilisées sous licence et sont des marques ou des marques déposées de SPARC International, Inc. UNIX est une marque déposée concédée sous licence par X/Open Company, Ltd.

Ce logiciel ou matériel et la documentation qui l'accompagne peuvent fournir des informations ou des liens donnant accès à des contenus, des produits et des services émanant de tiers. Oracle Corporation et ses affiliés déclinent toute responsabilité ou garantie expresse quant aux contenus, produits ou services émanant de tiers. En aucun cas, Oracle Corporation et ses affiliés ne sauraient être tenus pour responsables des pertes subies, des coûts occasionnés ou des dommages causés par l'accès à des contenus, produits ou services tiers, ou à leur utilisation.



Please
Recycle



Adobe PostScript

Contents

Preface ix

Sun Netra Data Plane Software Suite 2.1 Update 1 Release Notes 1

Open Issues 1

`gccfss` Shared Libraries Fail to Load When They Are Built With `gccfss`
Compiler (CR 6911428) 1

Compilation Fails if a Function Returns a Structure (CR 6529219) 2

`ipsecgw_niu_multi`: tx Rate Drops When Resuming to Execution After
Dropping Into Debugger (CR 6621914) 2

`ipsecgw_QGC`: “`nxge_desc_setup`: Cannot allocate rx buffer!”
Message Seen
(CR 6624475) 2

Ctrl+C Might Not Work Properly on an Application Built by
`ipsecgw_niu_multi` (CR 6637959) 3

`ipfwd10g_niu`: Performance Drops When Resuming to Execution from
Ctrl+C (CR 6670493) 3

`ipsecgw_niu_multi` on Netra T5220 – Packets Getting Dropped Even for
Lower Line Rates
(CR 6695813) 3

(W36) The `acltool` Hangs if Its Previous Invocation Was Interrupted by
Ctrl+C (CR 6713076) 3

`ipctest` Utility Subcommands Hang if Traffic Is Sending From the Traffic
Generator (CR 6717561) 4

`ipsec_niu_multi`: Takes a Few Minutes for the Numbers to Settle on Netra CP3260 (CR 6722105) 4
 Port0 of Ethernet Device Must be Opened First Before Port1 (CR 6724434) 4
`gdb` – Internal Error in Netra DPS Domain Might Happen When Using the `step` Command Followed by a Breakpoint (CR 6726490) 4
`ipctest` Utility Hangs When Doing `perf-pkts-rx-tx` (CR 6731036) 5
`ipfwd-diffserv`: Class-Based Scheduling Does Not Work Across DMA Channels (CR 6732966) 5
 NIU Does not Operate Correctly When Memory Allocated for Primary Domain Is Not Aligned (CR 6744977) 5
 Allowable Setup Example 5
 Non-Allowable Setup Example 6
 When 10G PCI-E Card Is Used, Each Port Must Allocate at Least 4 DMA Channels (CR 6760590) 6
`acltool` Does Not Issue Warning Messages for Invalid Parameters in Interactive Mode (CR 6767958) 6
 IP With GRE Forwarding Might Crash After GRE Entries in the GRE Table Are Purged (CR 6775156) 7
`ipfwd10g` Shows Inconsistent Performance Numbers on T5440 When Toggling Between 2 Ports (CR 6775168) 7
`acl` Reference Application Is Not Yet Supported on the Netra CP3260 System (CR 6786752) 7
 (T15148) `teja_get_error` Crashes During NDPS Application Memory Initialization (CR 6794685) 7
 Circular Buffer-Based Memory Pool Does Not Function Properly When Used With IP Forwarding Application (CR 6794705) 8
`ipfwd10g` 2 Ports Under Logical Domains - Performance Drops When Packet Size Increases and Resumes to the Same Size (CR 6843688) 8
`ipfwd_sync.d` Does Not Execute on Solaris 10 (CR 6843723) 8
 BSPL Can Have Memory Leak When Used in FIB Table Lookup (CR 6843725) 8

tnsmctl1 Might Need to Be Executed Every Time When NDPS (or LWRTE) Domain Restarts (CR 6844126)	9
ntgen and ipfwd Do Not Work Properly When Among of Memory Declared in Pool Declarations Reaches the Full Memory Capacity (CR 6846199)	9
ndpstgen Application	9
ipfwd Application	10
Some Tunneling Configurations Do Not Work With Two Ports (CR 6846840)	12
ipc_tx Crashes if the Message Buffer Address (mp->b_rptr) Is Not 32-Bit Aligned (CR 6873060)	12
IPv6 Ping Using lwmod Model Does Work for Other Ports Except the First Port (CR 6939385)	12
Limitations	13
Netra DPS 2.1 Update 1 Does Not Support the ipge Ethernet Interface	13
Limited Tests Have Been Done on CP3260 Equipped With the 10-Gbps ARTM	13
Netra ATCA CP3260 System Build Has Limited Hash Policy Options (CR 6702655)	13
10-G (10-G PCI-E Card) Option Is Not Yet Available for ipsecgw (CR 6708127)	14
All ipsecgw Application Options Are Statically Coded and Are Not Downloadable Through the build-with-LDoms Option (CR 6708140)	14
Profiler Supports CPU Counters Only (CR 6711351)	14
Jumbo Frame Is Not Supported on Ethernet Drivers (CR 6723585)	14
autoconfig – No Options to Modify Guest Domain (CR 6724105)	14
autoconfig – Does Not Check Existing File Under the /export Directory (CR 6724125)	15
autoconfig – Use Default Name Only for LDC Channel (CR 6724170)	15
Reference Applications Cannot Handle Non-Consecutive Ethernet Ports (CR 6762682)	15
autoconfig Does Not Provide a Command to Remove Domain (CR 6764230)	15

Limited Support for CP32x0 10-GBE ARTM (CR 6838876 and CR 6840226)	15
Remove the Hidden Inclusion of System Header Files From TejaCC (CR 6533446)	16
ipc_tx(): Chaining of Messages Is Not Supported (CR 6578957)	16
remotectl: Some Subcommands Are Not Yet Implemented (CR 6586372)	16
Reference Applications Cannot Handle Non-Consecutive Ethernet Ports (CR 6757600)	17
Trie algorithm is not supported in ACL v6 (CR 6932399)	17
RLP Application Cannot Handle Both vlan and Non-vlan Packets Dynamically (CR 6622138)	17
Configuring LM-X Licenses	17
Working With Licenses Using LM-X	17
Node-Locked Licenses	18
Obtaining a Node-Locked License File	19
▼ To Install a Node-Locked License	19
Evaluation Licenses	19
Obtaining an Evaluation-License File	19
Feedback and Support	20

Preface

This document contains late-breaking news and open issues for the Sun Netra Data Plane Software 2.1 Update 1.

This preface contains the following topics:

- [“Related Documentation” on page ix](#)
- [“Documentation, Support, and Training” on page x](#)
- [“Documentation Feedback” on page x](#)
- [“Documentation Feedback” on page x](#)

Related Documentation

The following table lists the documentation that is related to this product.

Application	Title	Part Number	Format	Location
Getting started	<i>Sun Netra Data Plane 2.1 Update 1 Getting Started Guide</i>	820-5158-11	PDF	Online
User	<i>Sun Netra Data Plane 2.1 Update 1 User Guide</i>	820-5154-11	PDF	Online
Reference	<i>Sun Netra Data Plane 2.1 Update 1 Reference Manual</i>	820-5156-11	PDF	Online

Documentation, Support, and Training

The Sun web site provides information about the following additional resources:

Sun Function	URL
Documentation	http://www.sun.com/documentation/
Support	http://www.sun.com/support/
Training	http://www.sun.com/training/

Documentation Feedback

Sun is interested in improving its documentation and welcomes your comments and suggestions. Submit comments about this document by clicking the Feedback[+] link at <http://docs.sun.com>.

Include the title and part number of your document with your feedback:

Sun Netra Data Plane Software Suite 2.1 Update 1 Release Notes, part number 820-5157-11.

Sun Netra Data Plane Software Suite 2.1 Update 1 Release Notes

These release notes contain last-minute information about Oracle's Sun Netra Data Plane Software Suite 2.1 Update 1 release. The Sun Netra Data Plane software is referred to in this document as Sun Netra DPS.

Topics include:

- ["Open Issues" on page 1](#)
- ["Configuring LM-X Licenses" on page 17](#)
- ["Feedback and Support" on page 20](#)

Open Issues

This section contains the open issues for the Sun Netra Data Plane software. These issues are under investigation.

`gccfss` Shared Libraries Fail to Load When They Are Built With `gccfss` Compiler (CR 6911428)

When building shared libraries with `gccfss`, the compiler adds references to functions provided by `libgcc_s.so.1`. The `libgcc_s.so.1` library is not available in the Oracle's Solaris 10 U6 Operating System (core software group installation).

This causes shared library load failure with following error:

```
ld.so.1: <application using shared lib>: fatal: libgcc_s.so.1: open failed: No such file or directory
```

This error can be observed by building TIPC Solaris socket libraries with `gccfss` and running TIPC applications.

Workaround: Do not use `gcc` with the `--share` option to create shared library. Instead use default Solaris OS linker (`/usr/ccs/bin/ld`) with the `-G` option to create shared library.

Compilation Fails if a Function Returns a Structure (CR 6529219)

Compilation fails if a function within an application returns a structure. This situation is due in part to private functions missing from `libc`.

Workaround: The function needs to return a pointer to the structure.

`ipsecgw_niu_multi`: tx Rate Drops When Resuming to Execution After Dropping Into Debugger (CR 6621914)

The `ipsecgw` application might show a performance drop when execution is resumed after dropping into the debugger.

Workaround: None

`ipsecgw_QGC`: “`nxge_desc_setup`: Cannot allocate rx buffer!” Message Seen (CR 6624475)

`ipsecgw` over QGC displays messages if traffic is already started before the application boots up. The application, however, is still able to receive and pass the traffic after all ports are initialized.

Workaround: None.

Ctrl+C Might Not Work Properly on an Application Built by `ipsecgw_niu_multi` (CR 6637959)

This behavior only occurs on the Sun Netra CP3260 system.

Workaround: None.

`ipfwd10g_niu`: Performance Drops When Resuming to Execution from Ctrl+C (CR 6670493)

`ipfwd10g_niu` performance drops when going from 1500 bytes to 64 bytes (either directly or gradually). This is seen on Oracle's Sun Netra CP3260 and Sun SPARC Enterprise T5120 and T5220 systems.

Workaround: None.

`ipsecgw_niu_multi` on Netra T5220 – Packets Getting Dropped Even for Lower Line Rates (CR 6695813)

For `ipsecgw_niu_multi` application on a Sun Netra T5220 system, there is some difference in the number of packets received by the ports when sending 100 percent line rate and when sending the number of packets that each packet size can handle.

Workaround: None.

(W36) The `acltool` Hangs if Its Previous Invocation Was Interrupted by Ctrl+C (CR 6713076)

The next invocation of `acltool` hangs if it is interrupted by Ctrl+C. This also occurs after a timeout when rules are still being inserted by Hicup.

Workaround: Ctrl+C is disabled by default when using `acltool`.

ipctest Utility Subcommands Hang if Traffic Is Sending From the Traffic Generator (CR 6717561)

The `ipc_test` utility may hang when the `perf-pkts-rx-tx` command is used with the single threaded application while traffic is exchanged with the Solaris module (`lwmod`) on another channel. After the first command hangs, subsequent calls in `ipc_test` will also hang.

Workaround: None.

ipsec_niu_multi: Takes a Few Minutes for the Numbers to Settle on Netra CP3260 (CR 6722105)

A slight degradation occurs when the application is first booted, but numbers settle a few minutes later.

Workaround: None.

Port0 of Ethernet Device Must be Opened First Before Port1 (CR 6724434)

When multiple ethernet ports are opened, the lowest number port number of the Ethernet port must be opened first.

Workaround: When opening a port from a application, the application needs to open the lowest port first.

gdb – Internal Error in Netra DPS Domain Might Happen When Using the step Command Followed by a Breakpoint (CR 6726490)

When in the Sun Netra DPS domain, an internal error might occur when you use the `step` command followed by a breakpoint.

Workaround: None.

ipctest Utility Hangs When Doing perf-pkts-rx-tx (CR 6731036)

The `ipc_test` utility hangs when the `perf-pkts-rx-tx` command is used while traffic is exchanged with the Solaris module (`lwmod`) on another channel.

Workaround: None.

ipfwd-diffserv: Class-Based Scheduling Does Not Work Across DMA Channels (CR 6732966)

Flows being transmitted on different DMA channels of the same port are not scheduled according to their respective weights or priority.

Workaround: None.

NIU Does not Operate Correctly When Memory Allocated for Primary Domain Is Not Aligned (CR 6744977)

When the starting physical address of the Sun Netra DPS domain is aligned on a 256-MB boundary, the NIU fails to receive packets into the specified memory locations.

Workaround: Make sure that the Sun Netra DPS domain memory is not aligned with a 256-MB boundary. If the Sun Netra DPS domain is the first domain bound after the primary domain, you can assign a multiple of 256-MB to the primary domain.

Allowable Setup Example

When 2-GB of memory are assigned to the primary domain, executing the `ldm ls -l` command for the Sun Netra DPS domain shows the following memory binding:

MEMORY		
RA	PA	SIZE
0x80000000	0x88000000	4G

The base PA of the Sun Netra DPS domain is 0x88000000 (which is not aligned with a 256-MB boundary).

Non-Allowable Setup Example

When 1920-MB of memory are assigned to the primary domain, executing the `ldm ls -l` command for the Sun Netra DPS domain shows this memory binding:

MEMORY		
RA	PA	SIZE
0x70000000	0x80000000	4G

The base PA of the Sun Netra DPS domain is 0x80000000 (which is aligned with a 256-MB boundary).

When 10G PCI-E Card Is Used, Each Port Must Allocate at Least 4 DMA Channels (CR 6760590)

When using a 10-Gbps PCI-E card, each port must be allocated with at least 4 DMA channels.

Workaround: Minimum of 4 channels must be allocated when building applications on 10-Gbps ports.

ac1tool Does Not Issue Warning Messages for Invalid Parameters in Interactive Mode (CR 6767958)

`ac1tool` does not issue any warning messages if the parameters are invalid. This behavior occurs only in interactive mode.

Workaround: None.

IP With GRE Forwarding Might Crash After GRE Entries in the GRE Table Are Purged (CR 6775156)

An IP with GRE forwarding might possibly crash after GRE entries are used after purging the GRE table.

Workaround: None.

ipfwd10g Shows Inconsistent Performance Numbers on T5440 When Toggling Between 2 Ports (CR 6775168)

ipfwd10g (which is ipfwd compiled with the 10g option) shows performance drops if toggling between 2 XAUI ports.

Workaround: None.

acl Reference Application Is Not Yet Supported on the Netra CP3260 System (CR 6786752)

The acl reference application is not currently supported on the Sun Netra CP3260 system.

Workaround: None.

(T15148) teja_get_error Crashes During NDPS Application Memory Initialization (CR 6794685)

When NDPS application declares memory pool in the heap of one of the strands being used and the size of the memory pool exceeds the size of the heap, then the application crashes when it is executed in NDPS logical domains.

Workaround: None.

Circular Buffer-Based Memory Pool Does Not Function Properly When Used With IP Forwarding Application (CR 6794705)

When memory is declared using the

`TEJA_GENERIC_MEMORY_POOL_SHARED_MEMORY_CIRCULAR_BUFFER` option, the `teja_memory_pool_get_node()` returns a NULL buffer node after a small number of memory nodes.

Workaround: Use other memory pool options.

`ipfwd10g` 2 Ports Under Logical Domains - Performance Drops When Packet Size Increases and Resumes to the Same Size (CR 6843688)

On T5440, when packet size is increased from 64-bytes to a larger size, then drops back to 64-bytes, performance can drop.

Workaround: None.

`ipfwd_sync.d` Does Not Execute on Solaris 10 (CR 6843723)

When executing the `ipfwd_sync.d` script on the Oracle's Solaris 10 Operating System (Solaris 10 OS), the script fails on `inet_ntoa6` and issues error messages about an undefined function name. This behavior does not occur when the script is executed on the Solaris 11 OS.

Workaround: None.

BSPL Can Have Memory Leak When Used in FIB Table Lookup (CR 6843725)

When using `teja_malloc()` option for BSPL lookup (passing NULL into `bspl_create()`), `bspl_add_prefix()` can cause memory leak.

Workaround: Pass hybrid memory into `teja_malloc()`.

tnsmctl Might Need to Be Executed Every Time When NDPS (or LWRTE) Domain Restarts (CR 6844126)

The `tnsm` drivers *remember* the `tnsmctl` setting so that every time when NDPS (LWRTE) domain restarts, `tnsmctl` does not need to be re-executed. However, in some conditions, `tnsmctl` must be re-executed when LWRTE restarts.

Workaround: Execute `tnsmctl` when an LWRTE domain is pending on its inputs.

ntgen and ipfwd Do Not Work Properly When Among of Memory Declared in Pool Declarations Reaches the Full Memory Capacity (CR 6846199)

This CR includes the behavior of two different applications: `ndpstgen` and `ipfwd`.

ndpstgen Application

The `ndpstgen` application does not boot on the T5440 with 10-Gbps Multithread PCIE Ethernet card and the T2000 with QGC when the following memory pools are created in the order mentioned:

1. Trace buffer pool (total = 1-GB)
2. Per-channel NxGE receive buffers (total = 16 * 25000 * 4096-B)
3. Common NxGE receive buffer pool (total = 20000 * 4096-B)
4. Per-channel mblk pools (total = 16 * 25000 * 4096-B)
5. Common mblk pool (total = 20000 * 4096-B)
6. Trace buffer metadata pool (total = 262144 * 8-B)
7. Packet info pool (total = 65536 * 8-B)
8. `mif_mutex`
9. `cls_mutex`
10. `eth_port_mutex`
11. `display_mutex`

12. mem64 (total = 10000 * 72-B)
13. mem128 (total = 10000 * 136-B)
14. mem256 (total = 10000 * 264-B)
15. mem512 (total = 10000 * 520-B)
16. mem1024 (total = 1000 * 1032-B)
17. mem2048 (total = 1000 * 2052-B)
18. mem4096 (total = 500 * 4104-B)
19. mem8192 (total = 500 * 8200-B)
20. mem10240 (total = 400 * 10248-B)
21. mem16384 (total = 200 * 16392-B)
22. mem20480 (total = 200 * 20488-B)
23. mem40960 (total = 100 * 40968-B)
24. mem65536 (total = 20 * 65544-B)
25. mem131072 (total = 10 * 131080-B)
26. mem163840 (total = 5 * 163848-B)

Normally, when the size of memory pools exceeds the size of the `dram_mem` memory pool bank set in `hwarch.c`, the following message is displayed when the application boots:

```
Too many data structures allocated to memory bank dram_mem. End of
memory bank dram_mem is at address 0x100000000 while last data
structure ends at address 0x1128e1240.
teja_main.c, 163: teja_early_system_init failed.
```

But, when the memory pools are created in the order mentioned, this message is not displayed.

ipfwd Application

The `ipfwd` application built to use logical domains does not pass packets on the T2000 (CMT1, 4 x 1-Gbps QGC) when the following memory pools are created in the order mentioned:

1. Trace buffer pool (total = 1-GB)

2. Common mblk pool (total = 200000 * 2048-B)
3. Common NxGE receive buffer pool (total = 200000 * 4096-B)
4. mif_mutex
5. cls_mutex
6. eth_port_mutex
7. display_mutex
8. gre_mutex
9. mem64 (total = 10000 * 72-B)
10. mem128 (total = 10000 * 136-B)
11. mem256 (total = 10000 * 264-B)
12. mem512 (total = 10000 * 520-B)
13. mem1024 (total = 1000 * 1032-B)
14. mem2048 (total = 1000 * 2052-B)
15. mem4096 (total = 500 * 4104-B)
16. mem8192 (total = 500 * 8200-B)
17. mem10240 (total = 400 * 10248-B)
18. mem16384 (total = 200 * 16392-B)
19. mem20480 (total = 200 * 20488-B)
20. mem40960 (total = 100 * 40968-B)
21. mem65536 (total = 20 * 65544-B)
22. mem131072 (total = 10 * 131080B)
23. mem163840 (total = 5 * 163848B)
24. mem327680 (total = 5 * 327688B)
25. ipv4_reasm_pool (total = 1024 * 64B)

Normally, when the size of memory pools exceeds the size of the `dram_mem` memory pool bank set in `hwarch.c`, the following message is displayed when the application boots:

```
Too many data structures allocated to memory bank dram_mem. End of
memory bank dram_mem is at address 0x100000000 while last data
structure ends at address 0x1128e1240.
teja_main.c, 163: teja_early_system_init failed.
```

Workaround: Ensure the platform has enough memory for the declared memory pool. Refer to the `ipfwd` and `ntgen` application for more information.

Some Tunneling Configurations Do Not Work With Two Ports (CR 6846840)

The `6in4` and `4in6` tunneling configurations do not work with the second port when the `ipfwd` application is compiled for two ports.

Workaround: None.

`ipc_tx` Crashes if the Message Buffer Address (`mp->b_rptr`) Is Not 32-Bit Aligned (CR 6873060)

A `ipc_tx` call results in a crash if the message buffer address (pointed to by `mp->b_rptr`) is not 32-bit aligned. `ipc_tx` needs 8 bytes of data for its own use. This space has to be reserved by the caller before the data buffer. `ipc_tx` calculates `b_rptr-8` as the byte address of the reserved space and then attempts a 64-bit (long-long) store at that address. Thus, if the data buffer address is not 64-bit aligned, a crash will occur.

Workaround: None.

IPv6 Ping Using `lwmod` Model Does Work for Other Ports Except the First Port (CR 6939385)

On multiple ports devices (for instance, dual 10G NIU or quad 4G PCI-E QGC card), an IPv6 ping works only for the first port when the `lwmod` model is used as the exception path mechanism.

Workaround: Use the `vnet` model for exception handling for IPv6.

Limitations

This section includes information about the known release limitations.

Netra DPS 2.1 Update 1 Does Not Support the `ipge` Ethernet Interface

This release does not support the `ipge` Ethernet interface. The `ipge` driver source code remains in the package for reference. Application supports the following Ethernet interfaces:

- Sun Multithreaded 10-Gbps Ethernet (PCI-E)
- Sun Multithreaded 4-Gbps Ethernet (PCI-E)
- Oracle's UltraSPARC T2 on chip the 10-Gbps Ethernet (NIU)

Limited Tests Have Been Done on CP3260 Equipped With the 10-Gbps ARTM

Sun Netra DPS has not been fully tested on the 10-Gbps NIU ports on the ARTM (Advanced Rear Transition Module).

Netra ATCA CP3260 System Build Has Limited Hash Policy Options (CR 6702655)

To build for running on Sun Netra ATCA CP3260 systems, `HASH_POLICY` options are limited to the following policies: `IP_ADDR`, `IP_DA`, and `IP_SA`.

10-G (10-G PCI-E Card) Option Is Not Yet Available for `ipsecgw` (CR 6708127)

For a 10-Gbps PCI-E card build, the `ipsecgw` application supports only 10-Gbps NIU build.

All `ipsecgw` Application Options Are Statically Coded and Are Not Downloadable Through the `build-with-LDoms` Option (CR 6708140)

Currently, `ipsecgw` application supports only a standalone environment. The `build-with-LDoms` option is not available for the `ipsecgw` reference application.

Profiler Supports CPU Counters Only (CR 6711351)

The current implementation of `perf_tools.c` does not collect DRAM counters from the UltraSPARC T1 and T2 processors, JBUS counters from the UltraSPARC T1 processor, and PCI-E counters from the UltraSPARC T2 processor.

Jumbo Frame Is Not Supported on Ethernet Drivers (CR 6723585)

The `nxge` Ethernet driver does not yet support Jumbo frame.

`autoconfig` – No Options to Modify Guest Domain (CR 6724105)

The `autoconfig` utility does not have an option to modify the guest domain. For example, while configuring the guest domain, if you forget to configure storage for `ldg1`, you cannot select the existing guest domain and modify it.

autoconfig – Does Not Check Existing File Under the /export Directory (CR 6724125)

The `autoconfig` utility does not check the existence of a file under the `/export` directory while adding the filename as backend to the virtual disk server device.

autoconfig – Use Default Name Only for LDC Channel (CR 6724170)

Configure LDC channels option creates the channels using default names between the domains. There is no option for the user to create the LDC channel names.

Reference Applications Cannot Handle Non-Consecutive Ethernet Ports (CR 6762682)

Reference applications assume hardware port numbers are consecutive, as in the following examples:

- `port0` and `port1` for NIU ports
- `port0`, `port1`, `port2`, and `port3` for QGC ports
- `port4` and `port5` for 10-Gbps ports

autoconfig Does Not Provide a Command to Remove Domain (CR 6764230)

The `autoconfig` utility does not have an option to remove a domain.

Limited Support for CP32x0 10-GBE ARTM (CR 6838876 and CR 6840226)

The 1-Gbps fiber ports on the CP32x0 10-GBE ARTM are not supported. The 10-Gbps PCI-E ports and 10-Gbps XAUI ports are supported. The 10-Gbps XAUI port support is being tested.

Remove the Hidden Inclusion of System Header Files From TejaCC (CR 6533446)

Currently TejaCC includes many hidden include files. While porting other OS kernel code to Teja, the code might include OS system files that might conflict with the files included by Teja. In this situation, the naming conflict can be resolved by modifying the naming of the data structures in the user applications.

ipc_tx(): Chaining of Messages Is Not Supported (CR 6578957)

Chaining of messages using the `b_next` field in the `mblk_t` structure is not supported in this release. `ipc_tx()` must be called once for every message.

remotecli: Some Subcommands Are Not Yet Implemented (CR 6586372)

```
sys> show
      show platform    - show platform
      show hostid      - show hostid
      show network     - show network
      show memory      - show memory
      show devs        - show all devs
      show cpus        - show all cpus
      show vars        - show all vars
      show ldom        - show ldom
      show mdesc       - show mdesc
      show ldc         - show ldc
```

The following subcommands are not yet implemented:

- show hostid
- show memory
- show vars
- show mdesc

Reference Applications Cannot Handle Non-Consecutive Ethernet Ports (CR 6757600)

Currently, reference applications can only handle Ethernet devices with port numbers that are consecutive.

Trie algorithm is not supported in ACL v6 (CR 6932399)

When using ACL for IPv6, the Trie algorithm is not supported. Use bsp1 algorithm instead.

RLP Application Cannot Handle Both v1an and Non-v1an Packets Dynamically (CR 6622138)

The default mode of RLP application does not handle vlan packets.

Configuring LM-X Licenses

This section include information about configuring the LM-X licenses.

Working With Licenses Using LM-X

You must have a license file to use the software. When you invoke compilation of any application, Sun Netra DPS reads the license file. A valid license file must be present at `/opt/LM-X/license`. Sun Microsystems issues two kinds of licenses:

- Node-locked licenses (multiple user) – see [“Node-Locked Licenses” on page 18](#).
- Time bound evaluation licenses (multiple user) – see [“Evaluation Licenses” on page 19](#)

Node-Locked Licenses

A node-locked license, or uncounted license, is a license that runs on a single machine. The license file contains permission to run various tools for multiple users simultaneously.

Obtaining a Node-Locked License File

To obtain a license file, email the following information to `NetraDPSlicense@sun.com`:

- User name, address, and company phone number of the license holder
- Product and target processor
- Purchase order number
- Host ID of the host computer where the distribution is installed

You can find the host ID by running `hostid` (located under `/usr/bin/`).

▼ To Install a Node-Locked License

1. **When you receive the license file (for example, `license`), copy it to the `/opt/LM-X/` folder.**
Create this folder if it is not present.
2. **Compile any of the reference applications or your own application to automatically find the license file.**
3. **Set the `LM_LICENSE_FILE` environment variable to include the location of the new license file.**

For example, in UNIX or Linux, use the `setenv` command in a C shell:

```
setenv LM_LICENSE_FILE /opt/LM-X/license
```

Evaluation Licenses

An evaluation license, or counted license, is a temporary license for a specified number of days. An evaluation license allows multiple users to use a single license file on a single computer for a limit of 90 days.

Obtaining an Evaluation-License File

To obtain an evaluation license file, email the following information to `NetraDPSlicense@sun.com`:

- Name of the license user (or contact name)
- Name, address, and phone number of your company

- Product and target processor
- The host ID of the host computer where the distribution is installed

You can find the host ID by running `hostid` (located under `/usr/bin/`).

Feedback and Support

You can request support and provide feedback to the following email address:

ndps-feedback@sun.com