



Sun StorEdge™ Network 2 Gb McDATA Sphereon 4300 Switch Release Notes

Sun Microsystems, Inc.
www.sun.com

Part No. 817-3635-10
September 2003, Revision A

Submit comments about this document at: <http://www.sun.com/hwdocs/feedback>

Copyright 2003 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. All rights reserved.

Sun Microsystems, Inc. has intellectual property rights relating to technology that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed at <http://www.sun.com/patents> and one or more additional patents or pending patent applications in the U.S. and in other countries.

This document and the product to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of the product or of this document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any.

Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, AnswerBook2, docs.sun.com, Sun StorEdge, SunSolve, and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the U.S. and in other countries.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc. Netscape is a trademark or registered trademark of Netscape Communications Corporation in the United States and other countries.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

U.S. Government Rights—Commercial use. Government users are subject to the Sun Microsystems, Inc. standard license agreement and applicable provisions of the FAR and its supplements.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

Copyright 2003 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, Etats-Unis. Tous droits réservés.

Sun Microsystems, Inc. a les droits de propriété intellectuels relatifs à la technologie qui est décrite dans ce document. En particulier, et sans la limitation, ces droits de propriété intellectuelle peuvent inclure un ou plus des brevets américains énumérés à <http://www.sun.com/patents> et un ou les brevets plus supplémentaires ou les applications de brevet en attente dans les Etats-Unis et dans les autres pays.

Ce produit ou document est protégé par un copyright et distribué avec des licences qui en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y en a.

Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux Etats-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, AnswerBook2, docs.sun.com, Sun StorEdge, SunSolve, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux Etats-Unis et dans d'autres pays. Les produits protégeant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc. Netscape est une marque de Netscape Communications Corporation aux Etats-Unis et dans d'autres pays.

L'interface d'utilisation graphique OPEN LOOK et Sun™ a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une licence non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciées de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui en outre se conforment aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISÉE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE À LA QUALITÉ MARCHANDE, À L'APTITUDE À UNE UTILISATION PARTICULIÈRE OU À L'ABSENCE DE CONTREFAÇON.



Please
Recycle



Contents

System Requirements 2

 Required Packages 2

 Required Patches 3

 ▼ To Download and Install the Patches 4

Optional Software and Support 4

Known Issues 5

Bugs 5

 Sun StorEdge McDATA Sphereon 4300 Switch Bugs 5

 Bugs With System Components With the Sun StorEdge McDATA Sphereon
 4300 Switch 7

Service Contact Information 7

Sun StorEdge Network 2 Gb McDATA Sphereon 4300 Switch Release Notes

This document contains important information about the Sun StorEdge™ Network 2 Gb McDATA Sphereon 4300 Switch with 5.05.00 firmware that was not available at the time that the product documentation was published. Review this document so that you are aware of issues or requirements that can impact the installation and operation of the products.

Note – Sun is not responsible for the availability of third-party Web sites mentioned in this document. Sun does not endorse and is not responsible or liable for any content, advertising, products, or other materials that are available on or through such sites or resources. Sun will not be responsible or liable for any actual or alleged damage or loss caused by or in connection with the use of or reliance on any such content, goods, or services that are available on or through such sites or resources.

This document contains the following main sections:

- “System Requirements” on page 2
- “Optional Software and Support” on page 4
- “Known Issues” on page 5
- “Bugs” on page 5
- “Service Contact Information” on page 7

System Requirements

The 5.05.00 firmware requires the use of these software products:

- McDATA SANpilot software
- Either of the following web browsers:
 - Netscape™ Communicator, versions 4.7 through 7.0
 - Microsoft Internet Explorer, 5.00.3315.1000x minimum

Required Packages

Certain software packages and patches are required for the Sun StorEdge SAN Foundation software and the Sun StorEdge Traffic Manager software for the Solaris Operating System (OS) to be supported on your SAN. For instructions to find, download, and install these packages and patches, see *Sun StorEdge SAN Foundation Software 4.2 Installation Guide*, 817-1244-xx.

Required Patches

You must download the appropriate Sun Solaris patches listed in TABLE 1 or TABLE 2 for proper switch operation. See “To Download and Install the Patches” on page 4 for installation instructions.

TABLE 1 Solaris 8 Patches

Solaris 8 Patches (-xx Minimum Version)	Description
111412-11	Sun StorEdge Traffic Manager software
111095-13	fctl/fp/fcp/usoc driver
111096-06	fcip driver
111097-12	qlc driver
111413-10	luxadm, liba5k, and libg_fc
111846-06	cfgadm fp plug-in library patch
111847-07	Sun StorEdge SAN Foundation kit
114877-01	JNI HBA patch for the Solaris 8 OS

TABLE 2 Solaris 9 Patches

Solaris 9 Patches (-xx Minimum Version)	Description
113039-03	Sun StorEdge Traffic Manager software
113040-05	fctl/fp/fcp/usoc driver
113041-03	fcip driver
113042-04	qlc driver
113043-03	luxadm, liba5k, and libg_fc
113044-03	cfgadm fp plug-in library patch
111847-07	Sun StorEdge SAN Foundation kit
114878-01	JNI HBA patch for the Solaris 9 OS

▼ To Download and Install the Patches

1. Access the SunSolveSM website at <http://www.sunsolve.sun.com>.

2. Under SunSolve Patch Contents, click Patch Portal.

3. Under PatchFinder, type the patch number and click Find Patch.

You do not have to type the version number (-xx). PatchFinder automatically finds the latest patch.

4. Verify the correct patch.

5. Click [Download Patch (xx,xxx bytes) HTTP FTP].

For additional patches, use your browser to return to the Patch Portal page.

6. Follow the instructions in the README file of each patch to install the patch.

Optional Software and Support

The McDATA Enterprise Fabric Connectivity Manager (EFCM) Lite, software 7.01.00 and earlier versions, is not supported with the Sun StorEdge Network 2 Gb McDATA Spheron 4300 Switch with 5.05.00 firmware. Use EFCM Lite version 8.xx.xx.

If you want full fabric visibility and management support with McDATA products, you must have the McDATA 4300 Full Fabric License Key. Contact your Sun sales representative to obtain the license.

Note – the “McDATA 4300 Full Fabric License Key” has also been referred to as the “Product Functional Enablement (PFE) Key for Full Fabric Upgrade for the McData Spheron 4300.”

Known Issues

An important issue described in the “Upgrade and Downgrade Considerations” section of the *McDATA Enterprise Operating System Release Notes, Version 05.01.00*, part number 958-000190, also applies to the Sun StorEdge McDATA Spheron 4300 switch. The contents of nonvolatile memory (NVRAM) on the active Control Processor (CTP) card (the CTP card with the bright LED) can become corrupted during firmware upgrading and downgrading.

Bugs

The bugs in this section are listed in order of priority (P) first, and then severity (S).

Sun StorEdge McDATA Spheron 4300 Switch Bugs

- **Bug 4854365 (P2/S3):** When connected to a JNI 2 Gb HBA and a Sun StorEdge 6910 or 6960 system, the Sun StorEdge McDATA Spheron 4300 switch can report an “Invalid Attachment” port state during repeated cable disconnects.
Workaround: Minimize cable disconnection between the Sun StorEdge McDATA Spheron 4300 switch and the HBA during operation.
- **Bug 4841884 (P3/S2):** During a diagnostic fault injection, a Sun StorEdge McDATA Spheron 4300 switch can lose its custom settings, such as the IP address and Flexport license, and return to the factory default settings.
Workaround: Perform a switch reset or power cycle. Then, reconfigure the IP address and reinstall the Flexport license.
- **Bug 4851117 (P3/S3):** A Sun StorEdge McDATA Spheron 4300 switch with a Gx_Port setting becomes a FL_Port when connected to a 1-Gb Fibre Channel device.
Workaround: Check the individual FL_Ports and manually set them to F_Ports.
- **Bug 4854340 (P3/S3):** During repeated cable disconnects, a Sun StorEdge McDATA Spheron 4300 switch can lose its Ethernet communication.
Workaround: Perform a soft reset with a CLI command through the serial port, or by pushing the IML/RESET button (IML is Initial Machine Load) on the front of the Sun StorEdge McDATA Spheron 4300 switch.

Note – The I/O operations continue during the soft reset.

- **Bug 4885300 (P3/S3):** A fabric boot fails with the error message “Can’t open boot device” when using JNI 2 Gb HBAs with the Sun StorEdge McDATA Sphereon 4300 switch Gx_Port settings.

Workaround: Set the ports on the Sun StorEdge McDATA Sphereon 4300 switch as a G_Port.

- **Bug 4832847 (P4/S4):** McDATA SANpilot with Microsoft Internet Explorer or Netscape Communicator displays only the first 50 characters of the firmware file names for download selection.

Workaround: Use McDATA Enterprise Fabric Connectivity Manager (EFCM) Lite, 8.xx.xx or later, to download firmware.

- **Bug 4848574 (P4/S4):** When the Storage Automated Diagnostic Environment is getting the error counters from a Sun StorEdge McDATA Sphereon 4300 switch, the software might report only the first five ports.

Workaround: Use the McDATA SANpilot software through the Microsoft Internet Explorer web browser, 5.00.3315.1000x minimum, to check the error status.

- **Bug 4765963 (P5/S4):** The deleteWnnMem command returns the response invalid zone name.

Workaround: Do not use the command-line interface (CLI) to perform zoning operations. Use McDATA SANpilot software accessed through the Microsoft Internet Explorer web browser, 5.00.3315.1000x minimum.

Bugs With System Components With the Sun StorEdge McDATA Spheron 4300 Switch

- **Bug 4747435 (P2/S2):** When the `cfgadm` command is used, an I/O failure occurs, and the Sun StorEdge T3 array is reported in an unusable state.

```
# cfgadm -al c4
```

Ap_Id	Type	Receptacle	Occupant	Condition
c5::50020f230000bfed	disk	connected	configured	unusable

Workaround: Check the integrity of the Sun StorEdge McDATA Spheron 4300 switch port cable connections, and ensure that the green port LEDs are lit.

- **Bug 4737352 (P2/S2):** When the `cfgadm -c configure` command is used, the Sun StorEdge T3+ array does not register its FC4-type to the Sun StorEdge McDATA Spheron 4300 switch.

Workaround: Use the `cfgadm -c configure` command with the `-f` force option.

```
# cfgadm -c configure -f device
```

- **Bug 4811576 (P3/S1):** When you disconnect a cable from the host to a Sun StorEdge McDATA Spheron 4300 switch, and you then reconnect it to another Sun StorEdge McDATA Spheron 4300 switch within the same fabric (using WWN zoning), the host stops functioning.

Workaround: Stop all I/O processes before removing the HBA cables.

Service Contact Information

If you need help installing or using this product, call 1-800-USA-4SUN within the United States, or go to:

<http://www.sun.com/service/contacting/index.html>

